

LTE5388-M804

Generic Version

Firmware Release Note

V1.00(ABSQ.2)C0

Date: Jun. 6, 2022

Author: Chin-Fu Ku

Reviewer:

THIS DOCUMENT CONTAINS PROPRIETARY TECHNICAL INFORMATION THAT IS THE PROPERTY OF THE ZyXEL AND SHOULD NOT BE DISCLOSED TO OTHERS IN WHOLE OR IN PART, REPRODUCED, COPIED, OR USED AS BASIS FOR DESIGN, MANUFACTURING OR SALE OF APPARATUS WITHOUT WRITTEN PERMISSION OF ZyXEL.

TABLE OF CONTENTS

Revision History	3
Modifications in 1.00(ABSQ.2)C0	6
Modifications in V1.00(ABSQ.2)b7	6
Modifications in V1.00(ABSQ.2)b6	6
Modifications in 1.00(ABSQ.2)b1	7
Modifications in 1.00(ABSQ.1)C0	8
Modifications in 1.00(ABSQ.1)b5	8
Modifications in 1.00(ABSQ.1)b4	8
Modifications in 1.00(ABSQ.1)b3	10
Modifications in 1.00(ABSQ.1)b2	10
Modifications in 1.00(ABSQ.1)b1	11
Modifications in 1.00(ABSQ.1)b0	12
Modifications in 1.00(ABSQ.0)C0	14
Modifications in 1.00(ABSQ.0)b3	14
Modifications in 1.00(ABSQ.0)b2	15
Modifications in 1.00(ABSQ.0)b1	16
Modifications in 1.00(ABSQ.0)b0	17

Revision History

Date	Release	Author	Description
2019/10/16	1.0	Chin-Fu Ku	V1.00(ABSQ.0)b0 fw release
2019/12/11	1.1	Chin-Fu Ku	V1.00(ABSQ.0)b1 fw release
2020/01/14	1.2	Chin-Fu Ku	V1.00(ABSQ.0)b2 fw release
2020/03/05	1.3	Chin-Fu Ku	V1.00(ABSQ.0)b3 fw release
2020/03/16	1.4	Chin-Fu Ku	V1.00(ABSQ.0)C0 fw release
2020/04/15	1.5	Chin-Fu Ku	V1.00(ABSQ.1)b0 fw release
2020/05/25	1.6	Chin-Fu Ku	V1.00(ABSQ.1)b1 fw release
2020/06/30	1.7	Chin-Fu Ku	V1.00(ABSQ.1)b2 fw release
2020/07/17	1.8	Chin-Fu Ku	V1.00(ABSQ.1)b3 fw release
2020/08/07	1.9	Chin-Fu Ku	V1.00(ABSQ.1)b4 fw release
2020/08/11	1.10	Chin-Fu Ku	Update the V1.00(ABSQ.1)b4 fw known issue and bug fix items.
2020/08/13	1.11	Chin-Fu Ku	V1.00(ABSQ.1)b5 fw release
2020/08/18	1.12	Chin-Fu Ku	V1.00(ABSQ.1)C0 fw release
2020/08/20	1.13	Chin-Fu Ku	V1.00(ABSQ.2)b1 fw release
2022/04/11	1.14	Chin-Fu Ku	V1.00(ABSQ.2)b6 fw release
2022/05/05	1.15	Chin-Fu Ku	V1.00(ABSQ.2)b7 fw release
2022/06/06	1.16	Chin-Fu Ku	V1.00(ABSQ.2)C0 fw release

ZYXEL LTE5388-M804 Generic V1.00(ABSQ.2)C0 Release Note

Date: Jun. 6, 2022

Supported Platforms

ZYXEL LTE5388-M804

Versions

Bootbase version : U-Boot 1.1.3 (Jul 26 2019 - 21:28:53)

Firmware version : V1.00(ABSQ.2)C0

Kernel version: 3.10.14

WLAN code version: V4.4.2.1_20170829

LTE Module FW version: EG12EAPAR01A07M4G

Firmware image information

Image	Version	File name	MD5 sum
Uboot Image-1: Pre-programming	U-Boot 1.1.3 (Jul 26	uboot-5388- 20190826.bin	513e972ffcad8c3188eaa96e741771c9
Uboot Image-2: Zyxel uboot update	2019 - 21:28:53)	100ABSQ2C0.bm	b994df11759c2a2cb67051f9b8a6ea91
FW Image	V1.00 (ABSQ .2) C0	100ABSQ2C0.bin	6c09642a8c9f4174bb1cc1c2709cb718

Notes:

There are two Bootbase files :

uboot-5388-20190826.bin is used for manufacturing
PROGRAMMER to program on the NAND flash

[100ABSQ2C0.bm](#) is for zyxel bootloader update usage, **This file with
zyxel header and must not directly program to flash. Wrong action will
cause the failure of boot.**

Default Settings in Firmware

- Refer to the *.rom in the fw release package.
- Refer to the *.config and *.predef for human readable default configuration.
- *.config define the default value of writable parameters, *.predef define the default value of read only parameters.
- Please use the website <http://jsoneditoronline.org/> to open the *.config and *.predef files.

Modifications in 1.00(ABSQ.2)C0

Based on the V1.00(ABSQ.2)b7 version , change to FCS version.

Modifications in V1.00(ABSQ.2)b7

[Configuration Modification]

N/A

[FEATURE ENHACEMENT]

N/A

[BUG FIX]

1. Issue #123: DUT can't work well while Roaming feature is off.

Modifications in V1.00(ABSQ.2)b6

[Configuration Modification]

N/A

[FEATURE ENHACEMENT]

1. Support Speed Test.
2. Support Neighbour Cells.
3. Update Italian language string.
4. Support Cell Lock.
5. Support TR-069 Delay Reboot.
6. The WEB admin and supervisor default login password is stored in the

MRD by random generate.

(MRD password index 1 and index 2)

[BUG FIX]

1. Fix the USB power control issue.
2. Fix that USB no unmount cause some wrong case.
3. [Vulnerability] clear text storage of sensitive information issue.
4. [Vulnerability] Infinite loop in BN_mod_sqrt() of OpenSSL when parsing certificates.

Update the OpenSSL to 1.1.1n

**** Skip the modifications for V1.00(ABSQ.2)b2 ~ V1.00(ABSQ.2)b5. ****

Modifications in 1.00(ABSQ.2)b1

[Configuration Modification]

N/A

[FEATURE ENHACEMENT]

1. Enable the Auto APN Multi Search feature.

[BUG FIX]

1. Issue 94: Even auto APN attach failed, UE always send first APN that meet PLMN in the apnlist.txt list and attempt to attach again.

Modifications in 1.00(ABSQ.1)C0

1. Change to FCS version.
2. Based on the 1.00(ABSQ.1)b5 version, remove the Auto APN Multi Search feature.

Modifications in 1.00(ABSQ.1)b5

[Configuration Modification]

N/A

[FEATURE ENHANCEMENT]

1. Add the Auto APN Multi search feature.

[BUG FIX]

1. Issue #91: When PPPoE with VLAN interface down and up, the device will not be able to access WebGUI/Telnet/SSH/Console, and the HW reboot/reset button function will be invalid.
2. Issue #92: GSM alphabet long SMS content display abnormal (GSM alphabet become Unicode)
3. Issue 94: Even auto APN attach failed, UE always send first APN that meet PLMN in the apnlist.txt list and attempt to attach again.

Modifications in 1.00(ABSQ.1)b4

[Configuration Modification]

N/A

[FEATURE ENHANCEMENT]

1. Change the APN search order for SFR mobile in apnlist.txt due to the front line request.

[BUG FIX]

1. Issue #31: SMS Inbox GSM alphabet content display abnormal (Char. become Unicode Hex) after received unicode content SMS.
2. Issue #61: If user hangs up immediately after making a call and repeats this action several times, the call status account will always accumulate and duration continue counting.
Software action: Use a workaround code to fix the repeats call cause the hardware SLIC abnormal issue.
3. Issue #76: UE can't display received SMS anymore after receiving a long SMS content.
4. Issue #77: Old SMS messages disappear (can't be displayed normal) if UE receiving a long SMS content.
5. Issue #78: System show the repeat message with specific condition and steps
6. Issue #80: UE-initiated Detach not work when device reboot or reset.
7. Issue #81: If user set the preferred Access Technology with invalid value "3G" or "4G" via TR-069 ACS, the setting will be applied and the Access Technology field displayed empty on WebGUI.
8. Issue #82: If user setting device not support LTE Band via TR-069 ACS, device will be applied the setting and disconnect with internet, need to setting the correct Cellular Band again.
9. Issue #85: The Website Blocked content is displayed empty on the Parental Control page.
10. Issue #91: When PPPoE with VLAN interface down and up, the device will not be able to access WebGUI/Telnet/SSH/Console, and the HW reboot/reset button function will be invalid.

Modifications in 1.00(ABSQ.1)b3

[Configuration Modification]

N/A

[FEATURE ENHACEMENT]

1. Add Ethernet WAN VLAN tag support.

[BUG FIX]

1. Issue #69: Short length packet may cause system call trace and reboot.

Modifications in 1.00(ABSQ.1)b2

[Configuration Modification]

N/A

[FEATURE ENHACEMENT]

N/A

[BUG FIX]

1. Issue #25: DHCP lease time is too long to wait with IP Passthrough Mode.
2. Issue #27: Select to Voice mode from VoIP to VoLTE, the VoIP status page still display "Register action" enabled and registered.
3. Issue #39: Enable Ethernet WAN (primary WAN) and disconnect LTE, the internet LED indicator will become "off"
4. Issue #42: WIFI password and SSID can't be empty or spaces.

5. Issue #64: The Parental Control Profile function not work normally.
6. Issue #67: Guest WiFi Settings display incorrect on home page.
7. Issue #68: Guest1~3 WiFi behavior not consistant after 2.4G/5G WiFi Setting disable and enable.
8. Issue #72: User can't disable IPPT mode if FIX mode didn't specify the MAC address.
9. Issue #73: WiFi SSID issue.
10. Issue #74: WiFi QR-Code issue.

Modifications in 1.00(ABSQ.1)b1

[Configuration Modification]

N/A

[FEATURE ENHACEMENT]

N/A

[BUG FIX]

1. Issue #14: System should show the current interface of WAN (Cellular/Ether WAN) when user operate.
2. Issue #23: When select the log level then pressing refresh on Web GUI, system will display all the category log. System should only display the assigned category.
3. Issue #33: CPE doesn't support IR-92 SS (Supplementary Services) and configurations.
There is no clarify VoLTE support function in PS document
4. Issue #34: While WAN IP change, VoIP service will lost register to server.
(EX: APN change or WAN back up active, Cellular WAN <=> Ethernet WAN)

- Need to disable and enable to register again.
5. Issue #36: WebGUI display wired connected devices under IP Passthrough mode abnormal.
WebGUI display "0" device while connecting two clients to LAN1 and LAN2 port under
IP Passthrough mode abnormal. (Please refer to remark picture)
 6. Issue #38: When Ethernet WAN fail over to Cellular WAN (Ethernet WAN backend disconnect), the WAN information still show Ethernet WAN IP on system info page.
 7. Issue 39: Enable Ethernet WAN and disconnect LTE, the internet LED indicator will become "off"
 8. Issue #43: Enable SMS inbox function will cause webGUI crash with FET SIM Card
After enable "SMS Inbox Enable", GUI pop-up Warning message "It is impossible to retrieve the information now. Please try again". (FET SIM Card only)
 9. Issue #48: WPS Method 3 mode fail issue.
 10. Issue #54: User cannot set SSID with special characters normally.
 11. Issue #67: Guest WiFi Settings display incorrect on home page

Modifications in 1.00(ABSQ.1)b0

[Configuration Modification]

N/A

[FEATURE ENHANCEMENT]

N/A

[BUG FIX]

1. Issue #2: Setting the lease time of DHCP server as 1 min but the lease time is 2 min when we capture the DHCP packet by Wireshark.
⇒ Change the minimal lease time to 2 minute.
2. Issue #22: System can't generate the any log on LAN PC.
3. Issue #24: Device should follow the Syslog Protocol "RFC 5424" to define the log category.
4. Issue #26: With IP Passthrough Mode, VoLTE function can't work and register to server, voice indicator LED also off.
5. Issue #28: DDNS could not active after CPE reboot.
6. Issue #32: Web word description error on Ethernet WAN setting page (LAN port4).
7. Issue #35: VoIP call waiting function abnormal. Need to reboot device.
8. Issue #39: Enable Ethernet WAN and disconnect LTE, the internet LED indicator will become "off"
9. Issue #40: Select VoLTE mode, enable Ethernet WAN and disconnect LTE, internet traffic passthrough by Ether WAN, but the voice LED indicator keep displaying "on".
10. #Issue 42: User can enter empty WIFI SSID and WIFI Password, and the setting could be applied successfully on home page (WiFi Settings).
Empty Password will become 64 character password automatically.
User can enter empty WIFI SSID, and the setting could be applied successfully on home page (Guest WiFi Settings).
11. Issue 47: WiFi Encryption key Input 64 charators and apply seting on WIFI page, the Encryption key will disappear.
12. Issue #49: Voice mode setting page disappeared except for English, user can't setting and select VoIP/VoLTE mode.
13. Issue #50: WIFI 2.4G Zyxel_63A5_guest3 invalid (BSSID 00:00:00:00:00:00).

14. Issue #53: In APN IPv6 enabled environment, the system will always crash during LTE connection after accumulating 128 times IPv6 Up and down.

Abnormal behavior of CPE under IPv4v6 dual stack is active.

The file, zcfg_tr98_map.json, is enlarged with appending IPv6 Addr/Prefix mapping while the IPv6 is active, but not removed from it while IPv6 is inactive.

15. Issue #62: WPS HW button function is not working

16. Issue #63: DHCP server only distributes one IP address when DHCP server pool setting 2 IP address.

17. Issue #67: The File Sharing Services is not working, and the power LED didn't displayed blue.

Modifications in 1.00(ABSQ.0)C0

[Configuration Modification]

Change the version number from 1.00(ABSQ.0)b3 to 1.00(ABSQ.0)C0

[FEATURE ENHACEMENT]

N/A

[BUG FIX]

N/A

Modifications in 1.00(ABSQ.0)b3

[Configuration Modification]

N/A.

[FEATURE ENHACEMENT]

1. Add VoIP/VoLTE feature.
2. Add SMS feature.
3. Improve the WebGUI display wired connected device under IP Passthrough mode.

[BUG FIX]

1. Fix the issue: Vulnerability: pppd vulnerable to buffer flow due to logic error.
2. Fix the issue: Ticket # 200200305 LTE3301-PLUS / Dynamic DNS problem

Modifications in 1.00(ABSQ.0)b2

[Configuration Modification]

N/A.

[FEATURE ENHACEMENT]

1. WAN backup feature.
2. Re-arrange the LAN/WAN icon to fit the real hardware position and label in the system info page.

[BUG FIX]

1. Fix the issue that WEB GUI does not show correct SCC information issue.
(Issue ID #7)

2. Fix the issue that when enable IP pass through mode, the internet LED abnormal.
(Issue ID #16)
3. Fix the issue that if the USB is plugged in before the device starts, the USB LED does not work properly.
4. Fix the issue that iPhone can't connect WIFI by scanning QR code.
(Issue ID #3)
5. Fix the issue that 5G WiFi SSID can't be searched by client with BW:20MHz.
(Issue ID #5)
6. Fix the issue for the WiFi client number setting cannot work properly.
(Issue ID #6)
7. Fix the issue that WebGUI doesn't display wired connected devices on IP Passthrough mode.
(Issue ID # 8)
8. Fix the issue for the WiFi WPS LED scenario.
(Issue ID #12, #13)
9. Fix the issue that about the command injection in Wifi SSID parameter setting.
(Issue ID: #1)

Modifications in 1.00(ABSQ.0)b1

[Configuration Modification]

1. Add new schema item for WAN backup.

[FEATURE ENHACEMENT]

1. Add WAN backup feature.
2. Add multiple-SSID feature.
3. Add Multiple-Language feature.
4. Support PCM test for manufacture.
5. Support new APP API.

[BUG FIX]

1. Fix the internet LED issue.
2. Fix the WEB GUI system info page LAN/WAN status incorrect issue.

Modifications in 1.00(ABSQ.0)b0

[Configuration Modification]

N/A

[FEATURE ENHACEMENT]

N/A

[BUG FIX]

N/A